

## **NYC Fire Marshall Report**



# FIRE AND INCIDENT REPORT

BUREAU OF FIRE INVESTIGATION, FDNY  
9 MetroTech Center Brooklyn, NY 11201


<input type="checkbox"/> ARREST	<input type="checkbox"/> PHOTOS TAKEN	<input type="checkbox"/> DRUG RELATED
<input type="checkbox"/> MULTIPLE ALARM	<input type="checkbox"/> JUVENILE INVOLVED	<input type="checkbox"/> WANTED CARD

BFI Case Number  
MAN 11193

Incident Location Hudson River—23rd St.		Incident Date 11/17/00		Incident Time 19:07		Incident Boro MANHATTAN		CB 4		BFI Command Reporting Manhattan Command	
FD Box No. 763		Batt Responsible for Report 9		Precinct 10		Complaint No.		Day of Week Friday		Weather clear/cool	
Response Code: 10-41		10-45		Notifications: <input type="checkbox"/> NYS Burn <input type="checkbox"/> Other		Incident Classification: Boat					
STRUCTURAL INFORMATION						AUTO INFORMATION					
Structure Size: 60 Foot Boat						Plate No.		State		VIN	
Stories N/A		Material Fiberglass		Make		Type		Year			
Owner of Structure or Vehicle N.Y. Waterways						Address of Owner Pershing Road Weehawken N.J. 07087					
Occupant or Tenant of Incident Location N.Y. Waterways						Occupied/Used as Ferry					
Date of Arrival at Incident 11/17/00		Time of Arrival 21:05		Fire Marshal Assigned Bucca							
Cause of Fire (Specify if Accidental). Heat from electrical equipment						Occupied/Vacant OCCUPIED					
ORIGIN		Floor N/A		Apartment N/A		Type of Room Engine Room		Check if Fire had Multiple Origins <input type="checkbox"/>			

## ORIGIN AND EXTENSION

Investigation disclosed and examination showed fire originated in the port side of the engine room in wiring harness located above the hydraulic control box. Fire further extended to ceiling and port side wall of the main deck. Fire was thereto confined and extinguished.



Signature of Assigned Investigator <i>[Signature]</i>		Tax Registry No.		Investigator Assisting	
SFM Name Printed Kelty		SFM Signature (BLUE INK ONLY) <i>[Signature]</i>		Date 11/26/00	

FI-101 9/98 MV